





CANOPY PROFILE BEAM ADJUSTMENT

DESCRIPTION

REVISIONS

FACILITY ENGINEERS

visiana National Guard Training Center Pineville

BLDG 6113 CANOPY REPAIRS

LAYOUT AND DETAILS

DRAWN BY: CW3 Michael Hanks

APPROVED BY: LTC Brian Plunk

26 September 2023 SHEET 1 OF 1